


From: Gary Shindy garyshindy@gmail.com  
Subject: Fwd: Require Assistance // GC 8890 // System Fault (Error Code 1000600a)  
Date: 22 September 2020 17:07  
To:



### Sequence:

Name	Vial	Method Path	Method File	Data Path	Data File	Type
MeOH	1	D:\MassHunter\GCMS1\methods	ST_T40_S50.M	D:\MassHunter\GCMS1\data\MN_GCMS	MeOH Trial	Sample

### System Fault (GC Interface):





249.99 %

View conditions

Close

**STATUS: ERROR**

Sequence

Method

Est. Remaining  
**39.67**



### System Fault - Please Reboot



Close

**Error Code** 1000600a

**Cause** An internal system fault occurred. One of the services within the instrument cannot be reached.


**Effect** Cannot execute runs. The integrity of any data collected going forward is not guaranteed.

**Suggested Resolution**

- Record the system unstable code above when preparing to contact Agilent.
- Attempt to reboot the instrument to rectify the fault.

System Fault - Code : 0x00100000

Reboot Now



## AFTER REBOOT:

